



Scan display

Sensors... Time range... Settings... Print... Show latest timestamp

Name	Number	Value	Name	Number	Value	Name	Number	Value	Name
Sensor #1	1	25,819 °C	Sensor #18	18	-84,824 °C	Sensor #35	35	-75,468 °C	Sensor #52
Sensor #2	2	▼ -18,235 °C	Sensor #19	19	-99,355 °C	Sensor #36	36	-39,919 °C	Sensor #53
Sensor #3	3	▼ -58,745 °C	Sensor #20	20	-94,575 °C	Sensor #37	37	3,389 °C	Sensor #54
Sensor #4	4	-87,838 °C	Sensor #21	21	-71,412 °C	Sensor #38	38	46,038 °C	Sensor #55
Sensor #5	5	-99,855 °C	Sensor #22	22	-34,368 °C	Sensor #39	39	79,738 °C	Sensor #56
Sensor #6	6	-92,464 °C	Sensor #23	23	9,356 °C	Sensor #40	40	97,940 °C	Sensor #57
Sensor #7	7	-67,100 °C	Sensor #24	24	51,261 °C	Sensor #41	41	97,105 °C	Sensor #58
Sensor #8	8	-28,694 °C	Sensor #25	25	83,203 °C	Sensor #42	42	77,396 °C	Sensor #59
Sensor #9	9	15,289 °C	Sensor #26	26	98,972 °C	Sensor #43	43	42,643 °C	Sensor #60
Sensor #10	10	56,301 °C	Sensor #27	27	95,504 °C	Sensor #44	44	-0,399 °C	Sensor #61
Sensor #11	11	86,369 °C	Sensor #28	28	73,473 °C	Sensor #45	45	-43,363 °C	Sensor #62
Sensor #12	12	▲ 99,650 °C	Sensor #29	29	37,160 °C	Sensor #46	46	-77,898 °C	Sensor #63
Sensor #13	13	93,561 °C	Sensor #30	30	-6,375 °C	Sensor #47	47	-97,293 °C	Sensor #64
Sensor #14	14	69,287 °C	Sensor #31	31	-48,671 °C	Sensor #48	48	-97,776 °C	Sensor #65
Sensor #15	15	31,545 °C	Sensor #32	32	-81,507 °C	Sensor #49	49	-79,254 °C	Sensor #66
Sensor #16	16	-12,328 °C	Sensor #33	33	-98,500 °C	Sensor #50	50	84,529 °C	Sensor #67
Sensor #17	17	-53,805 °C	Sensor #34	34	-96,348 °C	Sensor #51	51	28,062 °C	Sensor #68

Time of measurement: 26-jan-2016 11:49:00

Alarm

Sensors... Settings... **ALARM** Print... Acknowledge

Name	Number	Alarm	Value	Limit	First time	Last time	Ack.	Hits
1	Sensor #1	1	25,819 °C		26-jan-2016 11:42:00	26-jan-2016 11:45:00	no	4
2	Sensor #2	LW	▼ -18,235 °C	-15,000 °C	26-jan-2016 11:42:00	26-jan-2016 11:49:00	no	8
3	Sensor #3	LA	▼ -58,745 °C	-20,000 °C	26-jan-2016 11:42:00	26-jan-2016 11:49:00	no	8
4	Sensor #12	HW	▲ 99,650 °C	45,000 °C	26-jan-2016 11:42:00	26-jan-2016 11:49:00	no	8

Time of measurement: 26-jan-2016 11:49:00

Drag sensors here to temporarily disable alarm reporting
Drag back to resume